Work Order ID 57729 April 14, 2010 10:33:04 AM						,			Page 1
Item ID: D3564-5 Revision ID: Wearshoe	A	ccept				S	Setup Star		
Start Date: 14/04/2010 Start Qty: 10.00 Required Date: 22/04/2010 Req'd Qty: 10.00 Reference:			Cust Item II Customer:) :			Sto	P	
Approvals: Process Plan:	Date: 16-4-14	Tooling:	Dat	te:	_	F	Run Star		
QC:		SPC (Y/N):	Dat	te:			Sto	Р	
Sequence ID/ Operation Work Center ID Description		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr Revision Nbr		1.3	,						1
D3564 Rev D									
100 flow water jet		0.00	, .			181	0-4-7	1	
Waterjet FLOW CNC Waterjet 364.663 Memo 1-Cut as per Deburr if ne	Dwg D3564 □Dwg Rev:_cessary	0.00 ☐Prog Rev:	<u> </u>				<u> </u>	7	· ·
QC2- Inspect parts off m	achine FAI/FAIB	0.00				445			
QC Memo Quality Control	,	0.00				<u> </u>) <u>~4-7</u> 7		-
QC8- Inspect parts - seco	and check	0.00							
QC Memo Quality Control		0.00 D Tolor	X			(+10)			

W/O:			V	ORK ORDER CHANGE	S				<u> </u>	
DATE	STEP	PROC	EDURE CH	IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
			·							
	·									
•										
Part No	:	PAR #:	_ Fault Ca	tegory:	NCR: Yes	No DQ	A:	Date: _		
		esolution:								
NCR:	,	W	ORK OR	DER NON-CONFORMAN	ICE (NCF	?)		-		
DATE STEP	Description of NC		Corrective Action Section		Verific	Verification Approval				
	JIEI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section C		Chief Eng	Approval QC Inspector	
									}	
	,									
				·			V			

Wo	rk (Order	ID	57729
				-,,

April 14, 2010. 10:33:04 AM



Page 2

Item ID:

D3564-5

Revision ID:

Item Name: Wearshoe

Required Date: 22/04/2010

Start Date:

14/04/2010

Start Qty: 10.00 Req'd Qty: 10.00



Accept



Setup Start



Reject

Reference:

Approvals:

Process Plan: _____ Date: _____ Tooling:

QC: ______ Date: _____ SPC (Y/N):

Set Up/

0.00

0.00

Run Hours

Date:

Cust Item ID:

Customer:

Draw

Number

Date:

Draw

Rev.

Plan

Code

Start Run

Reject

Qty



Stop

Number Stamp

Insp.

Sequence ID/ **Work Center ID**

Brake NC

Brake NC

Memo

NC BRAKE

Operation

Description

Deburr if necessary | Form on Brake as per Dwg D3564 using Jigs DT8179 and DT8155 | Form Joggle as per Dwg D3564 on brake using Jig DT8157

140

QC

Quality Control

QC5- Inspect part completeness to step on W/O

0.00

0.00

Sidoubs

Accept

Qty

Ensure joggle as per dwg D3429

150

Powdercoat Powder Coating Grey Sandtex(Ref.4.3.5.6) per QSI005 4.3

Memo

1112588

0.00

0.00

=) Ist 10/04/30

Memo

START TIME: 7:0
7:30AN OFINISH TIME:

W/O:			W	ORK ORDER CHANG	ES					
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву		Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	egory:	_ NCR: Ye	es No	DQ/	A :	Date: _	
	R	esolution:	Disposition	on:	_ QA: N/C	Clos	ed:		Date:	
NCR:		•	WORK ORD	ER NON-CONFORMA	NCE (N	CR)				
DATE	STEP	Description of NC	Initial	Corrective Action Section		0	Verific	ation	Approval	Approval
DATE STEP	Section A	Initial Chief Eng	Action Description Chief Eng		n & ate	Secti	on C	Chief Eng	QC Inspector	
					:					
				···						

Work Order ID 57729

April 14, 2010 10:33:04 AM

Required Date: 22/04/2010



Page 3

Item ID:

D3564-5

Accept



Setup Start



Revision ID:

Start Date:

Item Name:

Wearshoe

14/04/2010

Start Qty: 10.00

Req'd Qty: 10.00



Cust Item ID: Customer:

Reference:

Approvals:	
------------	--

Process Plan: _____ Date: ____

QC: _____ Date:

Tooling:

SPC (Y/N):

Date: Date: Run

Start Stop

Stop



Sequence ID/ **Work Center ID**

160

Quality Control

Operation Description

QC3- Inspect Part Finish

Memo

Memo

Run Hours

0.00

Set Up/

0.00

Draw Number

Draw Plan Rev. Code

Accept Qty

Reject Qty

Reject Insp. Number Stamp

BR 10-4-30.

170

Packaging

Packaging

Identify as per dwg & Stock Location: FD-19 0.00 M 10/04/30

0.00

180

Quality Control

QC21- Final Inspection - Work Order Release

Memo

0.00

0.00

10/04/30 HJ ME, 1430

W/O:			W	ORK ORDER CHANG	ES			E ~ .
DATE	STEP	PROC	EDURE CHA	NGE	Ву	Date Q	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	_ Fault Cate	gory:	NCR: Yes	No DQA:_	Date: _	
	R	esolution:	_ Dispositio	n:	QA: N/C Cld	sed:	Date: _	
NCR:		W	ORK ORD	ER NON-CONFORMA	NCE (NCR)		
DATE STEP Description Section	Description of NC	Initial	Corrective Action Section		Verification	Approval		
	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector	
		4	, ,					
							ļ	

* Picklist Print

April 14, 2010 10:33:07 AM

Work Order ID: 57729

Parent Item:

Comments:

D3564-5

Parent Item Name:

Wearshoe

IPP Rev:A

New Issue 07-03-08 ec IPP Rev:B As per Rev C 07-07-09 JLM

IPP Rev:C IPP Rev D

As per Rev D 07-09-09 JLM Verified By:EC added DT# 08.04.21 DD Verified by EC

Start Date: 14/04/2010

Start Qty: 10.00

Required Date: 22/04/2010

Page 1

Required Qty: 10.00

M304S16GA

304/316 Sheet .063

Purchased

No

100

sf

16.5700 15.7895

四10-4-27

Warehouse Location

Main Warehouse

MAT20

113295

114467

Loc Oty

16.57

16.57

Loc Code

1(4467

	•									
W/O:			W	ORK ORDER CHANG	ES					<u> </u>
DATE	STEP	PRO	OCEDURE CHA	NGE	В	у	Date Qty Approval Chief Eng / Prod Mgr			Approval QC Inspector
						ļ				
Part No	•	PAR #:	Fault Cate	gory:	_ NCR: \	es N	lo DQ	A:	Date: _	
Resolution:										
NCR:			WORK ORD	ER NON-CONFORM	ANCE (N	ICR)			territ	
DATE	STEP	Description of NC			ion B		Verific	cation	Approval Approv	Approval
DATE		Section A	Initial Chief Eng	Action Description Chief Eng		gn & Date	Secti		Chief Eng	QC Inspector
		•								
									·	
				,						
								. 18 1		
										,

DART AEROSPACE LTD	Work Order:	57729
		· · · · ·
Description: Wearshoe	Part Number:	D3564-5
Inspection Dwg: D3564 Rev: D		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X	First Article		Prototype
---	---------------	--	-----------


Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
43.50	+/-0.030	43,50	7			
6.75	+/-0.030	6.15	1			
10.00	+/-0.030	10.00	V			
20.00	+/-0.030	20.00	u			
30.00	+/-0.030	30.00	8			***************************************
2.50	+/-0.030	3.60) ,			
3.227	+/-0.010	3.22-5	ъ			
38.500	+/-0.010	38,500	76			
5.500	+/-0.010	5.561	y			
2.50	+/-0.030	3,500	y			
2.432	+/-0.010	2,437	>			
0.300 x 0.300	+/-0.010	3064309	7			
Ø0.188	+0.005/-0.001	191	عر			
R0.375	+/-0.010	,315				
0.063	+/-0.010	1001	7			
_						
						-747

Measured by:	B	Audited by:	8.	Prototype Approval:	N/A
Date:	10-4-97	Date:	(doub) 8	Date:	N/A


Rev	Date	Change	Revised by	Approved
Α	08.01.16	New Issue	KJ/EC/DD	

Dart Aerospace Ltd	D	art	Aer	'OS	pace	Ltd
---------------------------	---	-----	-----	-----	------	-----


W/O:		WORK ORDER CHANGES										
DATE	STEP	PRO	OCEDURE CH	ANGE	·	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
				,								
				, m					·			
									·			
	1											
Part No:		PAR #:	Fault Cat	egory:	NCI	R: Yes						
	R	esolution:	Dispositi	Disposition: QA: N/C CI				losed: Date:				
NCR:			DER NON-CONFORM	ANCE	(NCR)						
DATE	CTED	Description of NC	Corrective Action Section B			<u>Ņ</u>	Verific	ation	ation Approval	Approval		
DATE STEP		Section A	Initial Chief Eng					on C	Chief Eng	QC Inspector		
. Anger												
								- <u>-</u>				
	,									,		



W/O:			WORK ORDER CHANGES								
DATE	STEP	PRO	CEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
Part No	:	PAR #:	Fault Cateo	gory:	NCR: Yes	No DQA	•	Date:	<u> </u>		
	Resolution: Disposition:					A: N/C Closed: Date:					
NCR:			WORK ORDE	R NON-CONFORMAN	CE (NCR)		,			
DATE	STEP	Description of NC	Corrective Action Section B			Verifica	ation	Approval	Approval		
DAIL SIE		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Sign & Section		Chief Eng	QC Inspector		
	-										
	1	1	i					£			
				·							



	•											
W/O:			WORK ORDER CHANGES									
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
ν												
Part No:		PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	A :	Date: _				
Resolution:			Dispositio	Disposition: QA:			QA: N/C Closed:					
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NC	₹)						
DATE	STEP	Description of NC		ion B	Verific	fication Approval		Approval				
	0.2.	Section A	Initial Action De Chief Eng Chief		ption Sign & Date		& Section C		QC Inspector			
							······································					
								į Į				
				•								
		•							ļ.			



W/O:		WORK ORDER CHANGES										
DATE	STEP	PRO	OCEDURE CHAN	IGE	By Date Qty Appr Chief Prod					Approval QC Inspector		
									. , ou mg.	-		
			7.4									
·									-			
Part No:		PAR #:	Fault Category: NCR: Yes No DQA:						Date:			
					QA: N/C Closed: Da							
NCR:				R NON-CONFORM								
	0750	Description of NC	Corrective Action Section B				Vorific	eation	Approval	Approval		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	ption Sign & Date			Verification Section C		QC Inspector		
			į									
	<u> </u>				-			185.8.2.1				